

Toyota is conducting a safety recall involving certain 2022 Lexus NX vehicles

April 13, 2022

PLANO, Texas (April 13, 2022) – Toyota is conducting a safety recall involving certain 2022 NX (including HEV, PHEV), vehicles in the U.S. Approximately 4,000 vehicles are involved in this recall.

The front shock absorbers in the affected vehicles are mounted to body panels that may be missing some spot-welds. Incorrect welding could eventually cause a shock absorber to separate from the mounting area, resulting in a loss of driving stability and increasing the risk of a crash.

For all involved vehicles, Lexus dealers will inspect the welding near the shock absorber mounting areas. For vehicles with missing spot-welds, additional welds will be added to the body panels. If the inspection determines that the body panels or any welds have failed, the body panels will be replaced.

Owners of involved vehicles will be notified by the middle of June 2022.

Information about automotive recalls, including but not limited to the list of involved vehicles, is current as of today's filing date and is subject to change thereafter. To see if your vehicle is involved in a safety recall visit Toyota.com/recall or nhtsa.gov/recalls and enter your Vehicle Identification Number (VIN) or license plate information.

For any additional questions, customer support is also available by calling the Lexus Brand Engagement Center (1-800-255-3987) for Lexus vehicles.

Updated on May 18, 2022