Toyota is Conducting a Safety Recall Involving Certain Toyota Vehicles

September 02, 2021

PLANO, Texas (September 2, 2021) – Toyota is recalling certain 2018-2021 Toyota Tundra vehicles produced between June 2017 through March 2021 in the U.S. Approximately 158,500 vehicles are involved in this recall.

The subject vehicles are equipped with halogen headlamps that allow the circuits for both the high and low beam bulb filaments to be energized at the same time when the high beams are switched on. Under some conditions, if the high beams are repeatedly left on for an extended period while the vehicle is idling or driving at low speed, there is a possibility that the bulb connector could overheat to a level that can result in an increased risk of a fire that can propagate to other parts of the vehicle.

For all involved vehicles, Toyota dealers will modify the engine wire harness assembly and inspect the headlight bulb connector, bulb and headlight assembly. If one or more of these components is found to be damaged due to this overheating condition, the damaged component(s) will be replaced with new ones as needed.

Owners of vehicles will be notified by November 1, 2021.

Information about automotive recalls, including but not limited to the list of involved vehicles, is current as of today's filing date and is subject to change thereafter. To see if your vehicle is involved in a safety recall visit Toyota.com/recall or nhtsa.gov/recalls and enter your Vehicle Identification Number (VIN) or license plate information.

For any additional questions, customer support is also available by calling the Toyota Brand Engagement Center (1-800-331-4331) for Toyota vehicles and Lexus Brand Engagement Center (1-800-255-3987) for Lexus vehicles.