

# **Toyota is conducting a noncompliance recall involving certain Tundra vehicles**

July 15, 2020

# TOYOTA

**PLANO, Texas (July 15, 2020)** – Toyota is conducting a noncompliance recall involving certain 2018-2020 Model Year Toyota Tundra vehicles in the United States. Approximately 183,000 vehicles are involved in this recall.

In the subject vehicles, the wire harness connected to the front turn signal bulbs was assembled incorrectly, causing them not to illuminate as brightly as intended. This can cause the subject vehicles not to comply with certain Federal Motor Vehicle Safety Standard requirements.

For all involved vehicles, Toyota dealers will modify the wire harness connected to the front turn signal bulbs at no cost to customers.

Owners of involved vehicles will be notified by mid-September 2020.

Information about automotive recalls, including but not limited to the list of involved vehicles, is current as of today's filing date and is subject to change thereafter. To see if your vehicle is involved in a safety recall visit [Toyota.com/recall](http://Toyota.com/recall) or [nhtsa.gov/recalls](http://nhtsa.gov/recalls) and enter your Vehicle Identification Number (VIN) or license plate information.

For the most up to date information surrounding recalls visit [nhtsa.gov/recalls](http://nhtsa.gov/recalls). For any additional questions, customer support is also available by calling the Toyota Customer Experience Center at 1-800-331-4331 or the Lexus Guest Experience Center at 1-800-255-3987.