

Toyota is conducting a safety recall involving certain Toyota vehicles

November 17, 2021

PLANO, Texas (Nov. 17, 2021) – Toyota is conducting a safety recall involving certain 2022 Sienna vehicles in the U.S. Approximately 2,300 vehicles are involved in this recall.

The subject vehicles are 8-passenger Siennas that were equipped with second row outboard seat belts that were manufactured with an incorrect component. This can increase the potential for the seat belt to “bunch” in the seat belt shoulder anchor in certain crashes, potentially causing the seat belt webbing to tear. This can increase the risk of injury in those crashes.

For all involved vehicles, Toyota dealers will replace the outboard second-row seat belt assemblies with ones that have been manufactured correctly, free of charge.

Owners of involved vehicles will be notified by mid-January 2022.

Information about automotive recalls, including but not limited to the list of involved vehicles, is current as of today’s filing date and is subject to change thereafter. To see if your vehicle is involved in a safety recall, visit Toyota.com/recall or nhtsa.gov/recalls and enter your Vehicle Identification Number (VIN) or license plate information.

For any additional questions, customer support is also available by calling the Toyota Brand Engagement Center (1-800-331-4331) for Toyota vehicles and Lexus Brand Engagement Center (1-800-255-3987) for Lexus vehicles.