Toyota Recalls Certain 2020-2023 Toyota Highlander, Highlander Hybrid Models

October 26, 2023

PLANO, Texas (Oct. 26, 2023) – Toyota is conducting a safety recall in the U.S. involving certain 2020-2023 model year Toyota Highlander and Highlander Hybrid vehicles. Approximately 751,000 vehicles are involved in this recall.

The subject vehicles are equipped with a resin front lower bumper cover assembly, connected with mounting tabs. If there is minor impact to the lower front bumper cover assembly that causes the mounting tabs to detach from the vehicle during normal operation, one or more parts of this assembly could detach, which could become a road hazard, increasing the risk of a crash or injury for other road users.

For all involved vehicles, Toyota dealers will inspect the upper to lower front bumper cover mounting tabs and slots for damage. If no damage is found, dealers will install retention hardware with an improved design. If damage is found, dealers will replace the upper and/or lower front bumper cover and install retention hardware with an improved design free of charge.

Toyota will notify affected owners about this issue by late December 2023.

Information about automotive recalls, including but not limited to the list of involved vehicles, is current as of today's filing date and is subject to change thereafter. To see if your vehicle is involved in a safety recall visit Toyota.com/recall or nhtsa.gov/recalls and enter your Vehicle Identification Number (VIN) or license plate information.

For any additional questions, Toyota customer support is also available by calling the Toyota Brand Engagement Center (1-800-331-4331).